**Charlotte Historic District Commission** 

Staff Review

HDC 2017-744

Application for a Certificate of Appropriateness

Date: January 10, 2017

PID# 08119706

LOCAL HISTORIC DISTRICT: Plaza Midwood

**PROPERTY ADDRESS:** 1927 The Plaza

**SUMMARY OF REQUEST:** Front porch columns and handrails

APPLICANT/OWNER: Ben Aycock

## **Details of Proposed Request**

### **Existing Conditions**

The existing structure is a one story ranch style home constructed in 1950. The front setback is 37'. Original porch supports were metal. A Notice of Violation was issued for work completed without a COA.

#### Project

The project is the replacement of the metal porch supports with squared wood columns, one centered and on the right corner. Column dimensions are 9" x 7". The handrails are an administrative review and will be corrected to meet the guidelines.

# Design Guidelines - Porches, page 6.14

- 1. Include a porch in the design of new residential construction when the majority of surrounding existing houses also contains a porch.
- 2. Design new porches to complement the size, proportion, placement and rhythm of existing historic porches within its context.
- 3. Ensure that the new porch is compatible with the overall architectural vocabulary/style of the new building.
- 4. Porches shall have a minimum depth of 8 feet.
- 5. Substitute materials are not allowed for front porch floors. Frame porches shall have tongue and groove floors laid perpendicular to front elevation of house.

## **Staff Analysis**

The Commission will determine if the project meets the guidelines for porches.

# Charlotte Historic District Commission Case 2017-744 HISTORIC DISTRICT: PLAZA MIDWOOD FRONT PORCH CHANGES Kennon St Belle Terre Av 1927 The Plaza Plaza Midwood **Historic District Property Lines** 120 240 360 **Building Footprints** January 4, 2018 ∎Feet







