Charlotte Historic District Commission
Staff Analysis

HDCRMI 2019-00514

Application for a Certificate of Appropriateness

Date: November 13, 2019

PID# 07101303

**LOCAL HISTORIC DISTRICT:** Wesley Heights

**PROPERTY ADDRESS:** 318 Grandin Road

**SUMMARY OF REQUEST:** Front Porch Addition

**APPLICANT/OWNER:** Paul and Laura Pearl

#### The application was continued from October for the following items:

• Accurate, proportionate to scale drawings of the front and side elevations, provide a beam and column detail, rowlock detail, and accurate drawings of the side porch roof

#### **Details of Proposed Request**

#### **Existing Conditions**

Known as the White House, the building is a 1.5 story Craftsman constructed in 1926. Architectural features include a front and side-gabled roof with an asymmetrical four-bay façade, 4/1 windows and front portico, supported by non-original fluted aluminum columns. Exterior materials are cedar shake and unpainted brick. Adjacent structures are 1 and 1.5 story single-family and multi-family buildings. Lot size is approximately 55' x 187.5'.

#### Proposal

The proposal is for changes to the front porch and a side porch. The front porch will be widened to 10' deep. All non-historic brick knee walls will be removed on both the front and side porches. Proposed materials are wood columns and trim, and a brick foundation to match existing. No changes to existing windows on the front, left, or right elevations are proposed. An enclosed side porch will be re-opened with columns and trim to match the front porch.

A TRAQ Qualified Certified Arborist, provided a letter documenting the 19" false cypress tree's structural defects, and was approved for removal, with replanting required, at the Administrative level.

#### Revised Proposal – November 2019

1. Revised drawings provided, including beam/column detail and rowlock detail.

#### Design Guidelines - Porches, page 4.8

- 1. Retain porches that are critical to defining the design and integrity of the historic district. Keep porches open to provide shade and reduce heat gain during warm weather.
- 2. Repair and replace only damaged elements of porches by matching the materials, methods of construction, and details of the existing original fabric. Avoid stripping porches and steps of original materials and architectural features such as handrails, balusters, columns, and flooring.
- 3. Reconstruct missing elements based on physical or photographic detail including all details and materials.
- 4. Do not enclose porches on a primary elevation or alter a front porch that reorients the entrance away from the street elevation.
- 5. Enclosure of side porches and balconies is discouraged. If enclosure of a side porch or balcony is required for a new use, the enclosure should be designed to ensure that the historic character and features of the porch are preserved.
- 6. Any porch enclosure that is permitted should be designed to be reversible and removal of original features should be minimal.

7. Original or historic porch railing designs may need to be adapted to meet the building code. The use of booster rails may be an appropriate solution to make the original balustrade code-compliant.

#### Design Guidelines – Porches, page 6.14

- 1. Include a porch in the design of new residential construction when the majority of surrounding existing houses also contain a porch.
- 2. <u>Design new porches to complement the size, proportion, placement, and rhythm of existing historic porches within this context.</u>
- 3. Ensure that the new porch is compatible with the overall architectural vocabulary/style of the new building.
- 4. Porches typically shall have a minimum depth of 8 feet.
- 5. Substitute materials are not allowed for front porch floors. Frame porches shall have tongue and groove floors laid perpendicular to front elevation of house.

#### <u>Design Guidelines – Additions, page 7.2</u>

- 1. Attempt to locate the addition on the rear elevation so that it is minimally visible from the street.
- 2. Limit the size of the addition so that it does not visually overpower the existing building.
- 3. Attempt to attach new additions or alterations to existing buildings in such a manner that, if such additions or alterations were to be removed in the future, the essential form and integrity of the building would be unimpaired.
- 4. Maintain the original orientation of the structure. If the primary entrance is located on the street façade, it should remain in that location.
- 5. Maintain the existing roof pitch. Roof lines for new additions should be secondary to those of the existing structure. The original roof as visible from the public right-of-way should not be raised.
- 6. Make sure that the design of a new addition is compatible with the existing building. The new work should be differentiated from the old while being compatible with its massing, form, scale, directional expression, roof forms and materials, foundation, fenestration, and materials.

All New Constructio	n Projects Will be Evaluated for Compatibility by the Following Criteria	Page			
Setback	in relationship to setback of immediate surroundings	6.2			
Spacing	the side distance from adjacent buildings as it relates to other buildings				
Orientation	the direction of the front of the building as it relates to other buildings in the district				
Massing	the relationship of the buildings various parts to each other				
Height and Width	the relationship to height and width of buildings in the project surroundings				
Scale	the relationship of the building to those around it and the human form				
Directional Expression	the vertical or horizontal proportions of the building as it relates to other buildings				
Foundations	the height of foundations as it relates to other buildings in project surroundings				
Roof Form and Materials	as it relates to other buildings in project surroundings				
Cornices and Trim	as it relates to the stylistic expression of the proposed building				
Doors and Windows	the placement, style and materials of these components				
Porches	as it relates to the stylistic expression of the proposed building and other buildings in the district.	6.1			
Materials	proper historic materials or approved substitutes				
Size	the relationship of the project to its site				
Rhythm	the relationship of windows, doors, recesses and projections				
Context	the overall relationship of the project to its surroundings.	6.1-			
Landscaping	a tool to soften and blend the project with the district	8.1-			

All projects should use this summary checklist to ensure a submittal addresses all the new construction criteria.

#### **Staff Analysis**

- 1. The proposal for the front porch is not incongruous with the District and meets the guidelines for Porches 4.8 and 6.15, Additions 7.2, and New Construction above.
- 2. Proposal is similar to previously approved front porch additions at 1910 Ewing Drive (2016) and 429 West Blvd (May 2019).
- 3. Minor revisions may be reviewed by staff.



## **HDCRMI 2019-00514**

PID: 07101303

LOCAL HISTORIC DISTRICT: WESLEY HEIGHTS PROPOSED PROJECT: ADDITION





# **Existing Conditions**









# **Existing Conditions**







# **Existing Conditions**







## Context/Adjacent Structures















# Context- Prior approved projects



429 West Blvd







1910 Ewing







## Setback in relation to neighbors












## Site Plan- Existing and Proposed



Front Elevation- Existing



# Submitted

## Front Elevation-Existing and Proposed



Preserve portico shape with arch and returns, extending to 10' deep and widening to 26' to preserve symmetry under front gable and book end each set of double windows.

Keeping 5' deep strip of sidewalk connecting front and side porch while removing non original brick rail. Repairing concrete floor as well as restoring brick steps to driveway, using matching brick.


## **NOVEMBER**

# Front Elevation- Proposed



## **NOVEMBER**

## Front Elevation- Proposed






## **Details**

Rowlock detail on current porch to be repeated on new porch (non-matching orange brick rail will be removed)

Rowlock to be flush with concrete porch. Note: this is the same appearance as current porch when unoriginal brick is removed



Tongue and groove soffit from original portico and is same on main house

Example of planned square non-tapered 8" column with cap/base and cove detail. (this is from another home on Grandin Rd).

Neck of column aligned with face of the beam.









### SUBMITTED OCTOBER

### Overhead dimensions



## SUBMITTED NOVEMBER


#### Overhead dimensions and detail



# Left Side Elevation- Existing and Proposed








## Right Side Elevation- Existing and proposed

to front door, see door detail

page




Non-matching brick to be removed



concrete, exposing chimney, door

and original window.



## Right side detail


Removal of vinyl and non original enclosure of porch and changing the columns to match the front of house. Restore/repair original window and replacing door (same as current front door) with one accurate to the time period, matching the front door replacement if possible. Repairing roof and installing black architectural shingles. Please note line where original brick and concrete floor is, with non matching brick installed on top.



### Front and Side Doors



Replace this unoriginal door on the left with this vintage 4 lite wood door that we will repair and matches the windows. Note how the door casing has been altered to decrease its height. We will restore the original door height.



## **Architectural Details**








Repair original 4:1 windows and salvage old glass when possible. Note strip of wood that has been cut from top trim to install the blue vinyl. Appears to have originally had upper trim like next door neighbor, which we would like to replicate.

Note 320 Grandin top trim piece. Similar piece was removed from 318 during vinyl installation.

Repair and replicate historic belly band detail between brick and cedar shake

Size	Bottom Diameter	Neck Dia	Cap/Base Molding Width	Cap/Base Molding Height	Max. Round Support	Max. Square Support
\	Α	В	С	E		
	5 %"	5 5/8"	8 1/8"	2***/	3 1/2"	3"
(8")	7 5/8"	7 5/8"	10 1/4"	((3 1/4"))	5"	4"
W Tolling	9 5/8"	9 5/8"	13"	500	7"	5"
12"	11 5/8"	11 5/8"	15 1/4"	4 1/2"	8"	6"
14"	13 5/8"	13 5/8"	18 %"	5 3/8"	10"	7"
16"	15 5/8"	15 3/8"	21 1/2"	6 1/4"	12 1/2"	8 1/2"
18"	17 5/8"	17 5/8"	24 1/8"	7 5/16"	14 1/2"	9 1/2"
20"	20"	20"	27"	8 1/8"	*	*
24"	24"	24"	32 1/2"	9 15/16"	*	*
30"	30"	30"	40 1/2"	12"	*	*

## **Architectural Details**



Preserve all eave returns



Repair and/or replace as needed original cedar shake siding



Concrete porch floor with brick border, using matching brick

Brick porch skirt, using matching brick Brick steps



New asphalt architectural shingle roof to main house with matching roof to be completed on the porch

