Charlotte Historic District Commission Staff Review

Application for a Certificate of Appropriateness June 12, 2013

ADDRESS OF PROPERTY: 1900 Thomas Avenue, Plaza Midwood Local Historic District HDC 2013-078

SUMMARY OF REQUEST: Front Addition

OWNER: Dee Blackburn

APPLICANT: Dee Blackburn

Details of Proposed Request: This house has an existing front porch. The shed roof has a bonnet element over the front door. A large chimney is prominent on the front of the house but the new addition will come in front of it with the upper part of a chimney remaining visible. Proposed plans show a front facing gable over the front porch with columns atop masonry piers. An addition to the front will become heated living space. The Commission Deferred the application for additional information. Revised plans now include a floor plan, front and side elevations, dimensions, and an exhibit that shows existing vs. proposed.

Relevant HDC Design Guidelines

Addition


Staff Analysis: The proposed details and materials and new front porch are appropriate to several Local Historic District neighborhoods. The Commission will have to determine if, on this particular house the proposed addition warrants the loss of the existing elements. It is said that the existing porch is not original to the house.

ADDITIONS


Additions to existing structures in Local Historic Districts have a responsibility to complement the original structure. Additions should reflect the design, scale and architectural style of the original structure. The following guidelines are intended to encourage addition designs that are compatible with the existing structure, while not fully mimicking the original design.

1. All additions will be reviewed for compatibility by the following criteria:


a. Size	the relationship of the project to its site
b. Scale	the relationship of the building to those around it
c. Massing	the relationship of the building's various parts to each other
d. Fenestration	the placement, style and materials of windows and doors
e. Rhythm	the relationship of fenestration, recesses and projections
f. Setback	in relation to setback of immediate surroundings
g. Materials	proper historic materials or approved substitutes
h. Context	the overall relationship of the project to its surroundings









BELLE TERRE AVENUE







BELLE TERRE AVENUE







1900 Thomas Ave Existing Elevation


This photo was taken a year ago. Since then the house has been painted and some shakes replaced. The current front porch is too dangerous to use and needs to be re-built. If something is not done soon the porch could collaspe.

The current bushes are not sized adequately for where they are located since they tend to grow to tall for the front of the house. This has become a safety issue as well.



P.O. Box 5643 Chartotle, NC 28299-5643 704-996-0732 704-526-8004





New North Elevation



Existing South Elevation



